




FA 35 EC Meter Instructions

Layout



Setup / Calibration

- Switch on Meter by pressing the ON/OFF Button.
- Unscrew Battery Protective Lid and carefully lift out the Battery compartment to allow access to the Calibration Screw.



- Remove Electrode Cap and place probe into EC Standard 2.76 solution.

- Using the Supplied Screwdriver twist the screw to adjust the EC value, twist clockwise to reduce the value and anticlockwise to increase the value.
- Adjust until the Value reads 2.76 (if using EC Standard 2.76).
- Your EC Meter is now ready to use.

For further instructions or hydroponics information please visit one of our stores today or visit www.3ch.co.uk or [click here](#).